

. .

.....



•

:

•

.

.

•

1	
3	:
10	:
10	1.2
10	2.2
12	3.2
12	4.2
18	5.2
21	:
	•
21	. 1.3
22	. 2.3
24	. 3.3
24	1.3.3
34	:
41	1.4
45	
51	

51 () 61 () 65 ()

4

II II

2008

Abstract Restoration Of Archaeologist Islamic Castles ''Chosen Models ''

Fuad A. Al- Tarawneh

Mu'tah University, 2008

Preservation and Maintenance techniques in Jordan, represented in the research Study Sites; the Castles of Showbak, Karak and Ajloun are criticized for numerous gaps and in convent practices, which entails a serious need to study and evaluate the previous preservation methods, in order to avoid some of the inappropriate techniques, and to propose newer ones.

The research, after conducting the needed analysis, using- X-ray of the samples, concluded the existence of calcite material, quartz particles, and Dolomite. Using the microscope, the research concluded the same results, where the calcite material was used as an adhesive component except for karak Castle where some straw ground poultry mortar were used in the preserved parts.

:

.

•

.

. ...

•

"XRF Techniques "

"X-Ray-Florescence "

."Petropraphic Microscopy" "

"Epoxy Resin "

.

.(403:1990)

.(14-13 :1992) .

.(23 :2002 18 :1990

•

(64:1989)

.(Price 1975: 330- 332)

.(152-1979:151)

II II

.(265 :1990

5

(Batchelor, 1978:10)

(235-2002:234)

н н

-266 :1990) .(267

.

.(Torraca 1981:50)

.(vasari 1967:18) .

(274 – 271 :1990) .

vitruvius Morgan Bees Wax Morgan). .(1960: 260 Vasari Cellini Borghini Eastlake " Dammar resin " Cera Colla " Eastlake pisano (Eastlake, 1960: 170) "Manares (Chromatography analysis)

.(Manares 1982: 104) .

1931

1964

: (2) -1

(5) -2

· (9) -3

(15 + 12) -4

:1972 82-81 :1989) (40

.(16 :1984)

: **1.2**

.(16 :1992)

2.2

и и

.(1996:184 54 :1978)

.(16-15:1990)

:
-1
-2
.
-3
-4
.(35:1992)

(45:1996).

.

.(36 :1992)

. 3.2

: : -1

:

· -

· -

.(30 :2002)

. 4.2 + + + -1

-2

-3 (38:2002) .1 .2 .3 .5 .6 .7 .(15-11:1975

:

.(133- 124 :2004)

"

·

15

```
- 173 :1979 )
                              .( 175
      (45-40:1981)
                                .1
                                .2
                                .3
                                .4
                                .5
                   .( 176 :1979 )
             . ()
```

· : -

.(171- 169 :2003)

: -

.(221 :2002) .

.(247 :2002)

- 18:1991)

.(23

. 10

)

(186 – 185 :2003 ()

.(44- 43:1991).
. () -

: .(16:2002)

Clayton, 1975:). .(Amoroso 1983: 13 12-13

.(294 –293 :2002)

.1

.2

. -3

. -4

-5

II II

```
-183:1979 )
                         .( Naddaf 2002: 32-33 184
                                               5.2
                      .( 45 :1991 )
```

.(54 :1991 297 2002)

59 :2004) .(84 :2000

Cronyon 1975:)
.(230

:

1.3 .(141-140 :2001 36 :1998 - 1 -2 -5 -6 -7 :2001 18:1998

22

.(103

-8 -9 -10 -11 -12 -13 .(Thiel,1993:36) 2.3 -1 .(Cronyon,1975:54)

23

-2

```
.(Bender,1974:74)
                                                            -3
               .(2001:116
                                                            -4
            (22)
                                             Burra charter
                                   1999
                                    (21)
                   )
:2003
                                    .(80:2004
                                                       67
                                 Petrographic Analysis. -1
                                    X- Ray Diffraction. -2
                                 Compressive Strength. -3
                                    Salt Crystallization. -4
                          Capillary Water uptake value. -5
                                  Density And porosity. -6
     .(145-2004:138
                              Lewis and Mecochie, 1994:145)
```

.(2004:10)

: 3.3

: 1.3.3

:

290:1968)

.(69:1987 24:1974 25: 1270

5-4:1974)

.(86-83 :1987

- 1 -2 -3 -5 -6 102:1969) 15:1982 4:1974 290 :1970 5 :1970 .(80-79:1987 (120)(230) (35) (1330) -100)

.(243 :1987) (250 (1115) (1100)

(Montrieal)
.(248-247 :2002 8 :1974)

1995

.(:1995)

:

.

-1

-2

. -3 . -4

-5

. -6

1.5

1995

2003 2002

.(10-2003:1 2002 1995)

130 1040

.(10 :2002

157

1261

1281 1274

.(47 -43 :1990)

.(1990:50)

1843 1839 .(2002) 2002

73 4 24

1184/ 580

(1987:16 23:1974)

.(122-114:1987)

1993

.

.(3-1 :1993)

.(1993:2

1837 1834 1546

:

2002

³ 600

8.5

.(:2002-1982

(96:2005 ,98 -97 :1996 (Hall, Banks 1963: 31 2005:70 (1 (2 (3

.(214 :1996

(Mortar, plaster and . Lime stone Caco3 salt) (Lime) %50 %10 %95 Sramek,1980,) %20 .(48-50 .(Peroni,1982:56)

.(Rossi,1976:34)

.(Mora,1984:67)

. –

·

,

.

5×5

. 2.5 – 1.5 X-Ray-Florescence

.(AL-Tarawneh 2002: 10, 15-11:2001 (1 (3 (4 (5 Hall, Schweizer . 12:2001 (6 .(Tollr,1973:53

"Petrographic Microscopy",

"Polarizing Microscopy"

.(2004:138 ,75 :1989)	
" Capillary Water Uptake Value	-1
:Measurem	ent"
:2004).	(144
" Compressue Strength"	-2
. (142 :2004)	-3

.(149 :2004)
	(1
•	(2
Buehler / Somel Dimond Saw	(3
. 2.5 – 1.5	(4
	(5
24 (AL-Naddaf 2002: 15)	
+ E - Poxy) "Asiton" " " E - Poxy 12 .(Asiton	_1
•	ب-
1000 800 500	-

"Nacl"

41

"XRF"

· : 1.4 .1

.2

.

.3

.4

. 6

. 7

 .11

-.

. - .1

. .2

.3

.4

.5

. .1

. .4

(2000) 2 (2002) (1990) (2003) (1979) (2001) 138 -103 (2001) .157 -139

(2003 - 1995) (1996) (2002) (1978)

```
(1998)
                                (1998)
                              (1970)
                 . (2002 - 1982)
                          .( 1995)
1
                                  (1970)
                              (1972)
                              (1975)
                           ( 2005)
                       (2002)
                         (2001)
                               (2000)
                          (1969)
            2
                            (1991)
```

(1998) (2003) (2004) (2002) (2002) (1990) (1981) (1974) (1990) 296-265 4 (1989) (1979)

(1984)

3 (1989) .99-81 (1992) (1996) (1970) 2+1 1270 .(1993) 8 (1968) (1987) (1960) 3 (1996) (643-491)

(1982)

- Al. Naddaf, Mustafa, (2002) Weathering Mechanisms Technical Investigation in Relation to the Conservation of the Sand Stone Monuments in Petra, Jordan, Berlin.
- Al-Tarawneh, K. Al-Kofahi and Shobaki, J. (2002) **Analysis of Jund** Coins Using XRF Techniques, Ages. Vol. 12, Part. I.
- Amoroso, G. Glovanni, Fassina, Vasco(1983) **Stone decay and conservealton, Amsterdam,** Netherland.
- Batchelor, E.(1978) Art Conservation Cincinnati Art Museum, Budapest.
- Bender, E. (1974) Geology of Jordan, Borntrager- Berlin.
- Clayton. K. M. (1975), **Weathering**. Long man, London and New York.
- Cronyon, J.M. (1975), **The Elements of Archaeological Conservation**, Routledge, London.
- Eastlsk, L.C.(1960). **Methods and Materials of Painting of the great Schools and Masters.** New York.
- Hall, E., Schweitzer, F, and Tollr, P. (1973), X-Ray Fluoresnee Analysis of Museum Object. A New Instrument Archaeometry Vol.15, Part, I.
- Hall, E, and Banka S. (1963) **X-Ray Fluoresce Analysis in Archaeology the Millprobe Archaeometry** Oxford, University.
- Lewis. D. W. McConchie David. (1994) **Analytical Sedimentology** Printed in the Unified Stated of America.
- Manares, R. R.(1982) On the Treatment of Stone Sculptures in the **Past**. Icomos. Rome.
- Mora, P. (1984) Conservation of Wall Paintings, London.
- Morgan, H. M. (1960), The Ten Books on Architecture, New York.
- Peroni, S., and Others (1983) Lime Based Mortars For the repair of Ancient Masonry and Possible Substatutes. In: Mortars Cements and Croute Used in the Conservation of Historie Buildings Symposium Rome. Italy.
- Price, C. A. (1975) Stone Decay and Preservation Chemietry in Britain. Britain.
- Rossi Manarsi, R. (1976) **The Conservation of Stone Centro Cesare, Gund Per La Conservazione Delle Sculture all Aperto**, Bologna.
- Sramek, T. (1980) **Determination of the Source of Surface Deterloration of Tombstone at the Old Jewish Cemetery in Prage**, London.
- Thiel, M. J. (1993) **Conservation of Stone and Other Materials**, Vol. I, Printed in Great Britain at the University Press, Cambridge.
- Torraca, Giorgio (1981) **Porous Building Material Science for Architectural Conservation** Icc Rome.
- Vasari, G. (1967) The Lives of Painters Sculptures and Architects, Florence.

()

Sample Name:Mortar

No.	Card		Chemical Formula
1	5-0586 CaCo3		Calcium Carbonate (Calcite, syn)
2			Potassium Magnesium Aluminum
			Silicate Hydr 2.78
		(/	/)

Sample Name::Mortar

No.	Card		Chemical Formu	la
1	5-0586 CaCo3		Calcium Carbona	ate (Calcite, syn)
2	65-8977 CoS		Cobalt Sulfide (J	aipurite, syn)
3	10-0493 KMg3 (Si3Al)010 (OH)2		Potassium Magn	esium Aluminum
			Silicate Hydr	2.78
	(/		/)

Sample Name:Stone

No.	Card	Chemical Formula
1	5-0586 CaCo3	Calcium Carbonate (Calcite, syn)
2	12-0197 (K, Na) Alsi04	Potassium Sodium Aluminum Silicate (Trika 2.63

()

Sample Name: Mortar

No.	Card	Chemical Formula
1	26-0918 KO.2Na0.8C1	Potassium Sodium Chloride (Halite
		Potass
2	65-9496 PbS	Lead Sulfide (Galena, syn)
3	6-0438 AgBr	Silver Bromide (Bromargyrite)
4	33-0311 CaS04.2H20	Calcium Sulfate Hydrate (Gypsum,syn)
5	10-0351 MgCr204	Magnesium Chromium Oxide
		(Magnesiochromit)
6	47-1743 CaC03	Calcium Carbonate (Calcaite) 2.71
	(/ /)


Sample Name: Stone.


No.	Card	Chemical Formula
1	5-0628 NaCl	Sodium Chloride (Halite, syn)
2	17-0456 AgSbS2	Silver Antimony Sulfide (Cuboargyrite sy)
3	6-0344 CuC1	Copper Chloride (Nantolite syn)
4	65-0309 ZnS	Zince Sulfide (Zince blend, syn)
5	46-1045 SiO2	Silican Oxide (Quartz, syn)
6	17-0548 FeSiO3	Iron Silicate (Clinoferrosilite, syn)
7	2-0714 (Ca, Mn) Co3	Calcium Manganese Carbonate (Calcite, man 2.95
	(()

Sample Name: Stone.


No.	Card	Chemical Formula
1	5-0586 CaCo3	Calcium Carbonate (Calcite, syn)
2	46-1045 SiO2	Silican Oxide (Quartz, syn)
3	6-0246 CuI	Copper Iodide (Marchite, syn)
4	22-0718 (Ca, Mn) Mn409, 3H20	Calcium Manganses Oxide Hydrate (Rancieit 3.46


(())







قلعة الشوبك : نموذج تحليل عينة حجارة .












نموذج تحليل عينة حجارة قلعة عجلون

()








قلعة عجلون : موقع طبو غرافي

()






منظر عام لقلعة الشوبك قبل أعمال الترميم " الجهة الشمالية الغربية "




منظر عام لقلعة الشوبك وتبدو بعض أعمال الترميم " الواجهة الغربية "







قلعة الشوبك الواجهة الشمالية للبرج الأول "ظهور بعض التصدعات في البرج"



قلعة الشوبك الواجهة الشمالية للبرج الأول " بعض أعمال الترميم "




قلعة الشوبك, الجدار الواصل بين البرجين الرابع و الخامس. " و بعض أعمال الترميم"









منظر عام قلعة الكرك " و ظهور بعض أعمال الوميم ".




منظر عام قلعة الكرك " بعض أعمال الوّميم بشكل كبير ".



منظر عام قلعة الكرك تصدعات و انهيارات قبل أعمال الترميم.




منظر عام قلعة الكرك من الداخل " قبل أعمال الترميم "




قلعة عجلون منظر عام " تبدو فيه أجزاء مرممة وأجزاء لم تشغلها أعمال الترميم "



فلعة عجلون منظر عام التجهيزات لأعمال الترميم



قلعة عجلون " الأقبية التي شملتها أعمال الترميم ".



قلعة عجلون منظر عام للتجهيزات لأعمال الترميم